January 14th 2022, OLSZTYN, POLAND.

We're happy to let you know that the official Polyend Tracker v1.5 firmware update is ready.

Amidst minor improvements and necessary bug fixes, there's a highlight new feature. Your Tracker can now save separate instruments with all their settings. This allows importing those instruments to other projects you're working on. And sharing them with other users.

New Features

– Tracker can now save separate instruments with all their settings. This allows importing those instruments to other projects you're working on.
– You can now select slices in sample playback Beat Slice mode by pressing the corresponding pads
– The "Step" function button label in Pattern Editor is now labeled "Step jump",

Bug Fixes

– Incorrect Fill range in certain settings is now fixed,
– Sample recorder wasn't recording if MIDI chord was playing,
– Un-deletable instrument after loading project from the previous version is now fixed,
– 1.5.0b1 regression: samples could be normalized to 0 after adding a new sample to the song,
– Fixed freeze after changing granular LFO settings,
– Bringing up the Instruments popup on the Tracker screen occasionally resulted in a flickering screen,
– Slice fill effect counted "From" and "To" ranges incorrectly,
– Tracker mixer's visual performance is now better,
– Removing OFF events revealed a left-over MIDI instrument on the track,
– Beat slices weren't fully displaying,
– "Render Selection" was sometimes inconsistent,
– Horizontal view mode edits weren't always refreshing correctly on-screen,
– Sample preview in Sample Recorder was sometimes distorted,
– Volume of fast rolls was increasing on the last step of a pattern,
– TSTP FX is not anymore interfering with song export,
– Tempo FX values below 40 were treated as T40,
– Current playing pattern wasn't always in sync with highlighted song slot on the Song screen,
– Sidechain limiter stopped working after playing sound in Sample Editor/Sample Recorder,
– Active Reverb was cut when Sample Recorder was entered, even if "No" was selected,
– Subtle Limiter attack and release sounded too short after device restart,
– Changing radio region to Japanese didn't apply until device restart,
– Part of the "Additional Info" bar was clearing when moving between Pattern Editor and other screens,
– Using Shift+Up to select contents of the current track selected all tracks instead when sequencer was running,

Download the firmware update file, and a free instruments example pack here.

Find the accompanying video here.

Sincerely,

Polyend